



Southeastern Area • 453 S. Carbon Avenue • P.O. Box 718 • Price, UT 84501-0718 • 801-637-1303

August 10, 1989

Doug Farnsworth 2130 South Shumway Lane Moab, Utah 84532

Re: Diverting Control Structure South Mesa - Mill Creek

Dear Doug:

It is my understanding that you have yet to install an operational diverting structure on Mill Creek for the South Mesa Diversion. I assumed this would be done by this time. I am writing to encourage you to pursue this matter to its completion. No water will be diverted in 1990 unless a structure is in place to allow for the accurate delivery of your water. The present method of diverting water is not acceptable.

Again, I would encourage your immediate attention and cooperation in resolving this situation. Our position is firm with regards to this matter. If you would like to discuss your plans, please feel free to contact me at your convenience.

Respectfully,

Mark P. Page Area Engineer

cc: Mill Creek Distribution System
Attn: Bob Byrnes, Commissioner
P.O. Box 248
Moab, Utah 84532

Division of Water Rights
Attn: Lee Sim, Director of Distribution
1636 West North Temple
Salt Lake City, Utah 84116